

LOCK CONNECTOR FOR PRINTED CIRCUIT BOARD  
USSN 09/850,206; Atty. Docket 1100-113  
Michael Chung-Ta Chiang, et al.

Page 1 of 21






FIGURE 1

19850206 - 040302




LOCK CONNECTOR FOR PRINTED CIRCUIT BOARD  
USSN 09/850,206; Atty. Docket 1100-113  
Michael Chung-Ta Chiang, et al.

Page 3 of 21



2020-04-09 90205360



2020-04-09 - 9002058600







Figure 5

09850206 - 0100302



09850206 - 040302






FIGURE 8




FIGURE 8

003040 002050 000000








FIGURE 9














09850206 • 040302






114850206 0440302








Page 18 of 21



008602006 • 040302



Page 19 of 21



09850206 0440302

2020-04-09 09:02:05Z 860






FIG. 25

L  
CONNECTOR FOR PRINTED CIRCUIT BOARD  
USSN 09/850,206; Atty. Docket 1100-113  
Michael Chung-Ta Chiang, et al.

Page 21 of 21

